

Area	Equipment	Supplier (where identified)	Priority	Defect	Action to take	When by	Status
Iver Heath Rec Ground	BMX Mound		1 High	General poor condition	Needs Council decision	End October 2022	On Track
Iver Recreation Ground	Shelter		1 High	Bench is corroded / damaged	Weld or replace (previously identified)		Complete
Iver Recreation Ground	BMX Mound		1 High	General poor condition	Needs Council decision	End October 2022	On Track
Iver Heath Rec Ground	Fitness - Leg Back Stretch		2 Med	Protruding bolt ends	Trim or cover (Previously identified)		Complete
Iver Heath Rec Ground	Fitness - Trinity Cycle		2 Med	Protruding bolt ends	Trim or cover (Previously identified)		Complete
Iver Heath Rec Ground	Fitness - Push Hands		2 Med	Protruding bolt ends	Trim or cover (Previously identified)		Complete
Iver Heath Rec Ground	Fitness - Pull Up Bars		2 Med	Protruding bolt ends	Trim or cover (Previously identified)		Complete
Iver Heath Rec Ground	Basketball Court	SMP (Playgrounds) Ltd	2 Med	Gate self closer leaving sharp edges	Repair	End August 2022	Complete
Iver Heath Rec Ground	Football Netting		2 Med	Damaged and Corroded	Numerous Remedial Repairs (Prev Identified) - Need council decision	On-going	In Progress
Iver Heath Rec Ground	Basketball Court	SMP (Playgrounds) Ltd	2 Med	General Maintenance	Remedial repairs (previously identified)	End August 2022	Complete
Iver Play Area	Seating		2 Med	Closeness of seat to fencing	Consider moving	End October 2022	On Track
Iver Play Area	Climber - Unit	Sutcliffe Play	2 Med	Maintainance	Revisit and Monitor - parts recently replaced	End August 2022	Complete
Iver Play Area	Rotator - Bowl	Sutcliffe Play	2 Med	Bearings	Refer to manufacturer for servicing	End July 2022	Complete
Iver Play Area	Swing - Basket - Toddler	Huck Nets (UK) Ltd	2 Med	Various maintenance	Refer to manufacturer for parts / servicing (prev Identified)	End September 2022	Complete
Iver Recreation Ground	Carousel - Overhead	HAGS	2 Med	General Condition	Refer to manufacturer for servicing	End August 2022	Complete
Iver Recreation Ground	Ball Court		2 Med	General condition	Review / refer to manufactuer for servicing	End February 2023	On Track
Iver Recreation Ground	Fitness Station		2 Med	Various maintenance	Seek supplier for service (Previously identified)	End August 2022	Complete
Iver Recreation Ground	Swing - Basket - Senior		2 Med	Inspection / potential repair	Refer to manufacturer (unknown) for manual	End August 2022	Complete
Iver Play Area	Swing - Junior - 2 Bay 4 Seat	Sutcliffe Play	2 Med	Various maintenance	Refer to manufacturer for parts / servicing	End October 2022	Complete
Iver Recreation Ground	Climber - Multi	Monster Play	3 Low	General Maintenance	Review / refer to manufactuer for servicing	End October 2022	Complete
Iver Recreation Ground	Agility - Overhead Rings	Big Toys	3 Low	Various maintenance	Refer to manufacturer for parts / servicing	End September 2022	Complete
Iver Recreation Ground	Seating		3 Low	Wear around seating	Monitor and repair	End October 2022	Complete
Iver Recreation Ground	Signage Poles		3 Low	General condition	Monitor and repair (1 has already been identified and repaired)	End October 2022	Complete
Iver Heath Play Area	Fencing and Gates		3 Low	General Maintenance	Repair	End June 2022	Complete
Iver Heath Play Area	Multiplay - Toddler	SMP (Playgrounds) Ltd	3 Low	Roof fixtures	Secure	End September 2022	Complete
Iver Heath Play Area	Swing - Junior - 1 Bay 2 seat	SMP (Playgrounds) Ltd	3 Low	Loose seat bolt	Tighten (previously identified)		Complete
Iver Heath Play Area	Carousel - Flush	HAGS	3 Low	Bearings - Stiff to use & noisy	Service (Previously identified)	End May 2022	Complete
Iver Heath Rec Ground	Junior Multiplay	Miracle Design & Play Ltd	3 Low	Fixture Loose or missing	Secure loose clamps	End August 2022	Complete
Iver Heath Rec Ground	Junior Multiplay	Miracle Design & Play Ltd	3 Low	Condition of protective ground surface	Repair	End August 2022	Complete

Iver Heath Rec Ground	Youth Shelter		3 Low	Bolt Cap Damaged	Replace	End September 2022	Complete
Iver Heath Rec Ground	Youth Shelter		3 Low	Worn Ground areas	Make good - build up to remove trip hazard	End September 2022	Complete
Iver Heath Rec Ground	Signage Pole		3 Low	Corroded Pole	Remove	End October 2022	Complete
Iver Play Area	Gates		3 Low	Buffer	Fit Buffer	End October 2022	Complete
Iver Play Area	Rocker - Jumbo	Ledon A/S	3 Low	Shrinkage of surface	Monitor and repair	End August 2022	Complete
Iver Play Area	Rocker - seesaw	Nijha B.V.	3 Low	Various maintenance	Monitor and repair	End August 2022	Complete
Iver Play Area	Swing - Toddler - 1 Bay 2 seat	Sutcliffe Play	3 Low	Various Maintenance	Refer to manufacturer for parts / servicing	End September 2022	Complete
Iver Play Area	Trampoline	Sutcliffe Play	3 Low	Various Maintenance	Refer to manufacturer for parts / servicing	End February 2023	On Track
Richings Park Play Area	Gates		3 Low	Trip hazard point	Liaise with RP sports club	End September 2022	Complete
Richings Park Play Area	Site Signage		3 Low	Signage - Dog ban	Order appropriate signage	End September 2022	Complete
Richings Park Play Area	Rocker - Seal	HAGS	3 Low	Loose fixture	Tighten	End August 2022	Complete
Richings Park Play Area	Swing - Junior - 2 Bay 3 Seat	HAGS	3 Low	Loose swing seat eye-bolt	Tighten	End August 2022	Complete