

Area	Equipment	Supplier (where identified)	Priority	Inspection Type	Defect	Action to take	When by	Status
Iver Heath Rec Ground	BMX Mound		1 High	Annual May 2022	General poor condition	Needs Council decision foollowing Residents Survey in 2023		In Progress
Iver Recreation Ground	BMX Mound		1 High	Annual May 2022	General poor condition	Needs Council decision foollowing Residents Survey in 2023		In Progress
Iver Heath Rec Ground	Football Netting		2 Med	Annual May 2022	Damaged and Corroded	Numerous Remedial Repairs (Prev Identified) Need council decision	On-going	In Progress
Iver Play Area	Seating		2 Med	Annual May 2022	Closeness of seat to fencing	Consider moving	On-going	On-going
Iver Recreation Ground	Ball Court		2 Med	Annual May 2022	General condition	Review / refer to manufactuer for servicing	End May 2023	On Track
Iver Play Area	Trampoline	Sutcliffe Play	3 Low	Annual May 2022	Various Maintenance	Refer to manufacturer for parts / servicing	End May 2023	On Track
Richings Park Play Area	Entry Gates		3 Low	Operational Mar 23	Trip Hazards	Complete remedial work to eliminate trip hazard at entry gate - liaising with RPSC	End June 2023	On Track
Richings Park Play Area	Multiplay Junior	HAGS	3 Low	Operational Mar 23	2 x missing bolt covers	Replace - parts ordered	End May 2023	On Track